

Snowdens Mill/Falling Creek Stream Restoration

Public Meeting
January 23, 2018



Introductions



- Beth Forbes, PE
 - Project Manager, Montgomery County DEP/JV
- Miranda Reid
 - Watershed Planner, Montgomery County DEP
- Lucia Noya, PE
 - Project Manager, Rummel, Klepper & Kahl, LLP (RK&K)
- Jason Coleman, PE
 - Project Designer, Rummel, Klepper & Kahl, LLP (RK&K)


Today's Agenda



- Watershed Management Overview
- Project Background
- Existing Conditions
- Restoration Design and Approach
- Construction: What to Expect
- Project Schedule and Next Steps

What is a Watershed?

- A watershed is an area from which the water above and below ground drains to the same place.
- Different scales of watersheds:
 - Chesapeake Bay
 - Potomac River
 - Anacostia River
 - Paint Branch
 - Snowdens Mill
 - Neighborhood-to a storm drain



Paint Branch Watershed



- Paint Branch is a Class III Stream
 - Growth and propagation of brown trout
- Special Protection Area (SPA)
 - High-quality/sensitive water resources or environmental features
 - Resources threatened by land use changes such as development
 - Developers must follow strict requirements
 - 10% Impervious cap



Paint Branch Watershed



- Paint Branch is a Class III Stream
 - Growth and propagation of brown trout
- Special Protection Area (SPA)
 - High-quality/sensitive water resources or environmental features
 - Resources threatened by land use changes such as development
 - Developers must follow strict requirements
 - 10% impervious cap




What is Runoff?

Water that does not soak into the ground becomes surface runoff. This runoff flows over **impervious** surfaces like rooftops, driveways and parking lots collecting potential contaminants and flows:

- Directly into streams
- Into storm drain pipes, eventually leading to streams
- Into stormwater management facilities, then streams


Two Major Issues:
Volume/Timing of Runoff
Water Quality





Runoff





Philadelphia Water Department

Urban vs. Forested Watersheds




Urban Mercer Creek

- Streamflow increases more quickly
- Higher Peak Flow
- Lower Baseflow
- Flash Floods
- Increased Erosion

Forested Newaukum Creek

- Lower peak flow slower to rise
- Higher base flow during periods of no rain → Supports fish




Land Use Change





























26% Impervious







Watershed 101



Impervious Surface Impacts to Streams




Stream in a watershed with **8%** impervious cover.


Stream in a watershed with **20%** impervious cover.





Stream in a watershed with **30%** impervious cover.





Habitat 101


Riffle/Pool Habitat & Good Baseflow





Poor/Low Baseflow

Habitat101



Riffle Habitat

- Oxygenation
- BenthicInvertebrates
- Fish Spawning



Embeddedness

- Sediment fills in riffles
- Low oxygen for organisms
- Poor habitat for benthics and fish

Habitat 101




Fish Cover/Bank Protection






Eroded/Incised Bank



What is the County Doing to Protect Streams?



- Must meet regulatory requirements
 - MS4 permit Municipal Separate Storm Sewer System
 - Provide treatment to 20% of County impervious area
- Watershed Restoration
 - Stream Restoration
 - Low Impact Development
 - Stormwater Pond Retrofits
 - RainScapes/Private Property Projects
- Monitoring/Evaluation
- Education and Outreach
- Special Protection Areas/Planning




Project Selection



- Located in a key watershed (Anacostia/Paint Branch Watershed) for stream restoration
- Erosion of banks threatening utilities and natural resources
- History of previous repairs
- Opportunity for water quality and ecological improvements
- Countywide Stream Protection Strategy and Lower Paint branch Watershed Study
- Anacostia River Watershed impaired for bacteria, PCBs, trash and debris, excess nitrogen and phosphorus, low dissolved oxygen, and excess sediment

Project Site











Typical conditions of Snowdens Mill channel in lower reach downstream of Serpentine Road





Snowdens Mill typical conditions in the Middle Reach (between Serpentine Way and Falling Creek Court) showing routine erosion of channel banks and under floodplain root zone







Eroded stream banks and invasive plants in Snowdens Mill Upper Reach (upstream of Falling Creek Road





Typical conditions of Falling Creek channel in lower reach downstream of Falling Creek Ct.





Routine erosion of channel banks and under floodplain root zone. Trees will eventually fall into the stream.





Eroded stream banks, debris, and invasive plants in Lower Falling Creek Reach





Channel migration to valley hill slope causing tree fall in lower section of Falling Creek (downstream of Falling Creek Court).

Restoration Goals



- Minimize natural resources impacts
- Improve aquatic & fish habitat
- Improve water quality
- Bed and bank stabilization
- Remove non-native invasive plants (vines/shrubs) within the stream LOD

Restoration Approach




Snowdens Mill

- Raise the existing stream bed elevation such that flood flows leave channel more-frequently to spread energy across floodplain
- Realign a portion of the channel in Snowdens Middle Reach (upstream of Serpentine Way) to prevent future erosion and tree fall
 - Create wetlands and wildlife habitat in abandoned channel

Lower Falling Creek

- Lower floodplain elevations such that flood flows leave channel morefrequently to spread energy across floodplain
- Create riparian wetlands in the lowered floodplain that are highlyconnected to groundwater


(01)- Snowdens Mill Upper Reach






(02)- Snowdens Mill Upper Reach






(03)- Snowdens Mill Upper Reach






(04)- Snowdens Mill Middle Reach






(05)- Snowdens Mill Middle Reach






(06)- Snowdens Mill Middle Reach






(07)- Snowdens Mill Middle Reach






(08) - Snowdens Mill Lower Reach






(09)- Snowdens Mill Lower Reach





(12)- Falling Creek Lower Reach





Riffle/Pool Sequence





Step Pool System





Imbricated Stone Wall





Toe Protection / Soil Lift






Log Grade Control





Rock Ramp





Woody Debris/Wildlife Habitat





Integrated Stream and Wetland System





Live Staking





Plantings





Reforestation





What to expect



Duration

- Approximately 6-12 months for each stream reach/area phased over two years
- Class III In-Stream Construction Closure Period Oct 1-April 30
- Construction Hours Monday Friday 7 AM 4 PM
- Safety
 - Open sides of site will be fenced with orange construction safety fence to separate construction from residents

Traffic

- Minor impacts to traffic from entering and exiting construction traffic and contractor parking during the day – traffic control
- Noise Comply with Montgomery County Noise Ordinance
- Sediment Comply with Montgomery County Sediment Control Permit

Construction Entrances



EXAMPLE





During Construction

After Construction

Construction Entrances

Sod Replacement





Staging Area





Erosion Control






In-Stream





Traffic Impacts





Restoration Monitoring



- County monitoring to evaluate whether project goals are achieved will continue five years after project completion.
 - In-stream Habitat
 - Aquatic Insects
 - Fisheries



Project Schedule



- Public Meetings December 5, 2017 / January 23, 2018
- Final Design Plans Fall 2018
- Construction Spring 2019 Fall 2020
- Cost estimated \$5,432,000 million financed by MCDEP CIP Program using funds generated through Water Quality Protection Charge



Questions?

For more information:

Miranda Reid 240-773-0802

Miranda.Reid@montgomerycountymd.gov

https://www.montgomerycountymd.gov/water/restoration/snowdens-mill-falling-creek.html

